AD-A257 611

FINAL REPORT **JUNE 1992**

REPORT NO. 92-10

AMMUNITION CERTIFICATION OF U.S. MARINE CORPS (USMC) M927A1 AND M923A1 TRUCKS



Distribution Unlimited

epared for:

mmander

S. Marine Corps Systems Command

TTN: SSCMT

antico, VA 22134-5080



VALIDATION ENGINEERING DIVISION SAVANNA, ILLINOIS 61074-9639

CHEMICAL COMMAND U.S. ARMY DEFENSE AMMUNITION

CENTER AND SCHOOL

AVAILABILITY NOTICE

A copy of this report will be furnished each attendee on automatic distribution. Additional copies or authority for reprinting may be obtained by written request from Director, U.S. Army Defense Ammunition Center and School, ATTN: SMCAC-DEV, Savanna, IL 61074-9639.

DISTRIBUTION INSTRUCTIONS

Destroy this report when no longer needed. Do not return.

Citation of trade names in this report does not constitute an official endorsement.

The information contained herein will not be used for advertising purposes.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE					Approved No. 0704-0188			
1a. REPORT SECURITY CLASSIFICATION				1b. RESTRICTIVE MARKINGS				
UNCLAS	SIFIED			<u> </u>				
2a. SECURITY CLASSIFICATION AUTHORITY				3. DISTRIBUTION / AVAILABILITY OF REPORT				
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE				UNLIMITED				
1	4. PERFORMING ORGANIZATION REPORT NUMBER(S)			5. MONITORING ORGANIZATION REPORT NUMBER(S)				
92-10								
6a. NAME OF PERFORMING ORGANIZATION			6b. OFFICE SYMBOL	7a. NAME OF MO	NITORING ORGANI	ZATION		
1	y Defense An	nmunition	(If applicable)					
Center an	d School y, State, and ZIP Co		SMCAC-DEV	7h ADDRESS (C)	the State and 718 Co	ada)		.
ATTN: S	MCAC-DEV	•		7b. ADDRESS (City, State, and ZIP Code)				
Savanna, 8a. NAME OF FUN	IL 61074-963		8b. OFFICE SYMBOL	9. PROCUREMEN	IT INSTRUMENT ID	ENTIFICAT	TION NUM	IRFR
ORGANIZATIO	N		(if applicable)					
	ine Corps Syst	tems	SSCMT					
Bc. ADDRESS (Cit		do)	550111	10 SOURCE OF	FUNDING NUMBER			
		<i></i>		PROGRAM	PROJECT NO.	TASK NO) .	WORK UNIT
ATTN: S		'000		ELEMENT NO.				ACCESSION NO.
	VA 22134-5			1		<u> </u>		
11. TITLE (Include	Security Classification	on)						
		on of U.S. Ma	rine Corps (USM	IC) M927A1 a	and M923A1	Trucks		
12. PERSONAL AL	JTHOR(S)							
A. C. Mc				T			т	
13a. TYPE OF REI	ORT	13b. TIME COVER	ED		PORT (Year, Month,	Day)	15. PAGE	COUNT
Final	ADVANOTATION	FROM	— то ——	1992 J	lune		<u> </u>	
16. SUPPLEMENT	ART NOTATION							
17.	COSATI CODES	•	18. SUBJECT TERMS	(Continue on reverse	e If necessary and ide	entify by bk	ock numbe	
FIELD	GROUP	SUB-GROUP	1	•	,	, ,		•
19 ABSTRACT (C	ontinue on reverse if	necessary and idea	tify by block number)					
,		•						
	•		nition Center and	•	•		_	_
			by the U.S. Mari					
M927A1 truck with a 20-foot International Organization for Standardization (ISO) bed and an M923A1								
truck with	a 14-foot car	go bed for cor	npliance with Tra	insportability	Testing Proced	lures, T	P-91-0	1,
July 1991. The procedures include rail impact and road transportation tests. Both vehicles satisfied the								
test requirements after hardware replacement and modifications were accomplished.								
- · · · · · · · · · · · · · · · · · · ·								
20. DISTRIBUTION / AVAILABILITY OF ABSTRACT 21. ABSTRACT SECURITY CLASSIFICATION								
	l			21. ABSTRACT SECURITY CLASSIFICATION				
WANTE OF RESPONSIBLE INDIVIDUAL				SSIFIFD (Include Area Code)	,	220 05	ICE SYMBOL	
			1		,			
JEROME H. KROHN				815-273	-8929		SMC	CAC-DEV

U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL VALIDATION ENGINEERING DIVISION

For

J. 34

Availability Codes

Avail and/or Special

SAVANNA, IL 61074-9639


REPORT NUMBER 92-10

AMMUNITION CERTIFICATION OF U.S. MARINE CORPS (USMC)

M927A1 AND M923A1 TRUCKS

JUNE 1992

TABLE OF CONTENTS



PART 1

INTRODUCTION

- A. <u>BACKGROUND</u>. The U. S. Army Defense Ammunition Center and School (USADACS), Validation Engineering Division (SMCAC-DEV), was tasked by the U. S. Marine Corps (USMC) System Command to test the M923A1 and M927A1 5-ton cargo trucks with 14-foot and 20-foot International Organization for Standardization (ISO) beds, respectively, for conformance to test requirements set forth in TP-91-01, Transportability Testing Procedures, July 1991.
- B. <u>AUTHORITY</u>. This test was conducted IAW mission responsibilities delegated by U.S. Army Armament, Munitions and Chemical Command (AMCCOM), Rock Island, IL 61299-6000. Reference is made to Change 4, 4 October 1974, to AR 740-1, 23 April 1971, Storage and Supply operations; AMCCOMR 10-17, 13 January 1986, Mission and Major Functions of U.S. Army Defense Ammunition Center and School.
- C. OBJECTIVE. The objectives of these tests are to validate the design criteria of the newly manufactured ISO beds for the M923A1 and M927A1 trucks. The new beds are equipped with ISO fittings for securing containers as well as regularly secured cargo. The transportation tests these loaded vehicles were subjected to include the following: rail, road hazard, road, panic stops, and washboard. Both vehicles were loaded to the maximum load capacity of 10,000 pounds.
- D. <u>CONCLUSION</u>. Both vehicles were tested during the 31 March 2 April 1992 timeframe. The M927A1 truck, with the 20-foot ISO bed, passed rail and road test procedures. The M923A1 truck failed the rail impact test when the rear bed mounts sheared from the truck chassis. A field fix, using 3/8-inch bolts also failed the rail impact test. A decision was made to

modify the rear body mounts to accept 1/2-inch bolts for securing the bed to the truck chassis.

This configuration was retested on 5 May 1992 and passed all transportation requirements.

- E. <u>RECOMMENDATIONS</u>. Based on the results of the tests performed on these vehicles, the following recommendations are offered:
- 1. The front shackles on each truck must be replaced as the ones delivered were not strong enough to secure the trucks in a rail transportation environment. The replacement shackle which was found to have adequate strength is NSN: 4030-01-222-6037.
- 2. Replace the body-to-chassis mounting bracket rivets with 1/2-inch UNF, grade 5 bolts on the M923A1 14-foot truck. The holes in the chassis and mounting bracket will have to be drilled to 17/32-diameter. This fix is necessary to ensure the body will remain fixed during rail shipment.
- 3. The removable sidewall stowage compartment covers must be strengthened. The strengthening can be accomplished by several longitudinal bends in the existing gate. During the rail impact test, the sidewall slid into the cover and deformed it. As a result of this deformation, it was difficult to remove the cover and could prevent accessing the sidewalls.
- 4. Two ball pins are used to retain the sidewall stowage compartment cover in place during vehicular movement. It was observed that these pins kept sliding out of the inside hole during the testing program. Further investigation showed that the inside holes were larger in diameter than the outside holes. The larger inside diameter prevented the pins from locking in position. Future production should ensure the following:
 - (a) These holes are the correct diameter.
 - (b) Holes are drilled correctly so the locking pin can be inserted correctly.

PART 2

ATTENDEES

31 March-2 April 1992, 5 May 1992

Captain John Mayles Commander

DSN 278-4281 U.S. Marine Corps Systems Command

703-640-4281 ATTN: SSCMT

703-640-4287 Quantico, VA 22134-5080

A. C. McIntosh, Jr. Director

General Engineer U. S. Army Defense Ammunition Center

DSN 585-8989 and School

815-273-8989 ATTN: SMCAC-DEV

E-Mail: amcintos@savanna-emh1.army.mil Savanna, IL 61074-9639

Richard S. Haynes Director

Industrial Engineering Technician U. S. Army Defense Ammunition Center

DSN 585-8225 and School

815-273-8225 ATTN: SMCAC-DET

Savanna, IL 61074-9639

Ron Kirchofner* Turtle Mountain Manufacturing Company

710-477-6404 Highway 5 West

P.O. Box 770

Belcourt, ND 58316

Dan Healy Association of American Railroads/

Senior Inspector Bureau of Explosives
708-392-6846 309 North Douglas Avenue

Arlington Heights, IL 60004

Quinn D. Hartman Director

General Engineer U. S. Army Defense Ammunition Center

DSN 585-8992 and School

815-273-8999 ATTN: SMCAC-DEV

E-Mail: qhartman@savanna-emh1.army.mil Savanna, IL 61074-9639

David V. Valant
Electronics Technician
DSN 585-8988
815-273-8988
E-Mail: dvvalant@savanna-emh1.army.mil

* Not present on 5 May 1992.

Director

U. S. Army Defense Ammunition Center and School

ATTN: SMCAC-DEV Savanna, IL 61074-9639

PART 3

TEST PROCEDURES

- A. These test procedures are extracted from TP-91-01, Transportability Testing Procedures,
 July 1991, for tactical vehicles used for shipping munitions by tactical truck or tactical truck on a
 railcar.
- B. The test load was prepared using the same blocking and bracing methods specified in the tiedown procedures proposed for use with the munitions. A copy of these procedures is contained in part 6 of this report. The truck used in this test was inspected to ensure its adequacy for munition transport. Items used to build the load were inert (nonexplosive). The weight and physical characteristics of the load configuration was identical to the live (explosive) ammunition provided for in the tiedown procedure; i.e., weights, physical dimensions, center of mass, materials, etc. The ammunition packages duplicated that of the live ammunition.


C. Tests for this set of load configurations is as follows:

- 1. Rail impact (test method no. 1).
- 2. Hazard course (test method no. 2).
- 3. Road trip (test method no. 3).
- 4. Hazard course (test method no. 2).
- 5. Washboard course (test method no. 6).

D. The Test Methods used are as follows:

- 1. Test Method No. 1 (Rail Impact Test). The test load or vehicle was positioned in/on a railcar. For containers, the loaded container was positioned on a container chassis and securely locked in place using the twist locks at each corner. The container chassis was secured to a railcar. Equipment needed to perform the test included the specimen (hammer) car, five empty railroad cars connected together to serve as the anvil, and a railroad locomotive. These anvil cars were positioned on a level section of track with air and hand brakes set and with the draft gears compressed. The locomotive unit pulled the specimen car several hundred yards away from the anvil cars and, then, pushed the specimen car toward the anvil at a predetermined speed, then disconnected from the specimen car approximately 50 yards away from the anvil cars which allowed the specimen car to roll freely along the track until it struck the anvil. This constituted an impact. Impacting was accomplished at speeds of 4, 6, and 8.1 mph in one direction and at a speed of 8.1 mph in the opposite direction. The 4 and 6 mph impact speeds were approximate; the 8.1 mph speed was a minimum. Impact speeds are to be determined by using an electronic counter to measure the time required for the specimen car to traverse an 11-foot distance immediately prior to contact with the anvil cars (see figure 1).
- 2. <u>Test Method No. 2 (Hazard Course)</u>. This step required the loads transported on the USMC truck be driven over the 200-foot-long segment of concrete-paved road which consisted of two series of railroad ties projecting 6-inches above the level or the road surface. The truck traversed this course two times.
- 3. <u>Test Method No. 3 (Road Trip)</u>. The USMC truck was used to transport loads for a distance of 30 miles over a combination of roads surfaced with gravel, concrete, or asphalt. The test route included curves, corners, railroad crossings, cattle guards, and stops and starts. The truck traveled at the maximum speed suitable for the particular road being traversed, except as

ASSOCIATION OF AMERICAN RAILROADS (AAR) STANDARD TEST PLAN



5 BUFFER CARS (ANVIL) WITH DRAFT GEAR COMPRESSED AND AIR BRAKES IN A SET POSITION ANVIL CAR TOTAL WT 250,000 LBS (APPROX)

SPECIMEN CAR
IS RELEASED BY
SWITCH ENGINE TO

ATTAIN: IMPACT NO. 1 @ 4 MPH

IMPACT NO. 2 @ 6 MPH IMPACT NO. 3 @ 8.1 MPH

EN THE CAR IS DEVERSED AND


THEN THE CAR IS REVERSED AND RELEASED BY SWITCH ENGINE TO

ATTAIN: IMPACT NO 4. @ 8.1 MPH

limited by legal restrictions. Upon completion of the 30-mile road trip, the loaded truck was subjected to three full airbrake stops while traveling in the forward direction and one in the reverse direction. The first three stops were at 5, 10, and 15 mph, while the stop in the reverse direction was approximately 5 mph.

4. <u>Test Method No. 6 - (Washboard Course)</u>. The USMC truck loaded with MILVAN/SIXCONs was driven over the washboard course (figure 2) at a speed which produced the most violent response of the vehicle. The washboard course is constructed as shown in figure 2.

FIGURE 2



PART 4

TEST RESULTS

TEST SPECIMEN AND RESULTS

RAIL IMPACT DATA

Test No.: 1

Date: 31 March 1992

Specimen Load: M927A1 5-ton long bed truck equipped with ISO corner fittings transporting a MILVAN loaded to 10,000 pounds.

Flatcar No.: BN 600108 Lt. Wt.: 46,900

5-Ton Truck Long Bed Wt.: 25,035

Container Type: MILVAN Wt.: 10,500

Total Specimen Wt.: 84.535

Buffer Car (five cars) Wt.: 250,000

Impact	End Struck	<u>Velocity</u>	Remarks:
1	Forward	4.46	Shackle on the vehicle left rear spreading. Sheared off safety pin.
2	Forward	6.70	Additional shackle spread. Still holding.
3	Forward	8.33	Shackle yielded and cables loose. Replaced shackle and retested.
4	Forward	8.24	Cable held. No damage to vehicle.
5	Reverse	8.33	No damage.

Note: Tiedown Shackles mounted on the front of the truck were replaced with NSN 4030-01-222-6037. These shackles are heavier and do not spread from impulse loads encountered during rail impact testing of the 5-ton class of vehicles.

TEST SPECIMEN AND RESULTS

ROAD TEST DATA

TEST NO.: 2 DATE: 31 March 1992

Specimen Load: M927A1 5-ton long bed truck equipped with ISO corner fittings transporting a MILVAN container.

ROAD HAZARD COURSE:

PASS 1-A OVER FIRST SERIES OF TIES: 0.11 MIN 5.16 MPH

PASS 1-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

PASS 2-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH

PASS 2-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

30-MILE ROAD TEST: No load movement or visible damage to the vehicle or load.

PANIC STOP TEST: No panic stops were done since this load was previously rail impact tested.

PASS 3-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.68 MPH

PASS 3-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.31 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

PASS 4-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH

PASS 4-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

TEST SPECIMEN AND RESULTS

ROAD TEST DATA

TEST NO.: 3

DATE: 31 March - 2 April 1992

Specimen Load: M927A1 5-ton long bed truck loaded with two MLRS pods configured two high and secured with web straps.

ROAD HAZARD COURSE:

PASS 1-A OVER FIRST SERIES OF TIES: 0.11 MIN 5.16 MPH
PASS 1-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement.

PASS 2-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH

PASS 2-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement.

30 MILE ROAD TEST: No load movement.

PANIC STOP TEST: No load movement.

PASS 3-A OVER FIRST SERIES OF TIES: 0.08 MIN 7.10 MPH

PASS 3-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.31 MPH

REMARKS: No load movement.

PASS 4-A OVER FIRST SERIES OF TIES: 0.10 MIN 5.68 MPH

PASS 4-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.31 MPH

REMARKS: No load movement.

WASHBOARD COURSE: No load movement greater than 1/2-inch. Load weight 10,000 pounds.

TEST SPECIMEN AND RESULTS

RAIL IMPACT DATA

Test No.: 4 Date: 1 April 1992

Specimen Load: M923A1 5-ton truck with two SIXCONs loaded to 5,000 pounds each.

Flatcar No.: BN 600108 Lt. Wt.: 46,900

5-Ton Truck Wt.: 22,175

Container Type: Two SIXCONs Wt.: 10,000

Total Specimen Wt.: 78,175

Buffer Car (five cars) Wt.: 250,000

Impact	End Struck	Velocity	Remarks:
1	Forward	4.12	No damage.
2	Forward	6.15	No damage. Severe deflection of vehicle at center on impact.
3	Forward	8.24	Failure. Rear riveted body mounts sheared off on both sides of the truck. Field fix is replace rivets with 3/8-inch UNF grade 5 bolts.
4	Forward	4.21	No damage of repaired mounts.
5	Forward	6.20	Failure. Bolts used to fasten rear body mounts to truck chassis sheared.

Note: Tiedown shackles mounted on the front of the truck were replaced with NSN 4030-01-222-6037. These shackles are heavier and do not spread from impulse loads encountered during rail impact testing of the 5-ton class of vehicles.

TEST SPECIMEN AND RESULTS

RAIL IMPACT DATA

Test No.: 5 Date: 5 May 1992

Specimen Load: M923A1 5-ton truck with two SIXCONs loaded to 5,000 pounds each.

Flatcar No.: BN 600108 Lt. Wt.: 46,900

5-Ton Truck Wt.: 22,175

Container Type: Two SIXCONs Wt.: 10,000

Total Specimen Wt.: 78,175

Buffer Car (five cars) Wt.: 250,000

Impact	End Struck	<u>Velocity</u>	Remarks:
1	Forward	4.55	No damage.
2	Forward	6.30	No damage.
3	Forward	8.43	No damage.
4	Reverse	8.72	No damage to repaired mounts.

Note: a. Tiedown shackles mounted on the front of the truck were replaced with NSN 4030-01-222-6037. These shackles are heavier and do not spread from impulse loads encountered during rail impact testing of the 5-ton class of vehicles.

b. Rear body mounts secured to the truck chassis with U.S. manufactured 1/2-inch UNF grade 5 bolts torqued to approximately 70 ft-lbs.

TEST SPECIMEN AND RESULTS

ROAD TEST DATA

TEST NO.: 6 DATE: 5 May 1992

Specimen Load: M923A1 5-ton truck with two SIXCONs loaded to 5,000 pounds each.

ROAD HAZARD COURSE.

PASS 1-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH

PASS 1-B OVER SECOND SERIES OF TIES: 0.11 MIN 5.16 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

PASS 2-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH

PASS 2-B OVER SECOND SERIES OF TIES: 0.10 MIN 5.68 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

30-MILE ROAD TEST: No load movement or visible damage to the vehicle or load.

PANIC STOP TEST: No panic stops were done since this load was previously rail impact tested.

PASS 3-A OVER FIRST SERIES OF TIES: 0.12 MIN 4.73 MPH

PASS 3-B OVER SECOND SERIES OF TIES: 0.09 MIN 6.31 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

PASS 4-A OVER FIRST SERIES OF TIES: 0.09 MIN 6.31 MPH


PASS 4-B OVER SECOND SERIES OF TIES: 0.11 MIN 5.16 MPH

REMARKS: No load movement or visible damage to the vehicle or load.

WASHBOARD COURSE: No load movement or visible damage to the vehicle or load.

PART 5

PHOTOGRAPHS



U.S. ARMY DEFENSE AMMUNITION GET/10-14 SCHOOL - SAVANNALIE

Photo No. A0317-SPN92-180-1595. This is a proton prevent 5-ton truck. The truck is loaded with a MBLVAN normalise of truck bed. The lading is 10,000 pounds. Note of trace of the compartment cover plate. This was caused by the confidence of rail impact. Deformation of the cover prevents remains a considerable walls.




Photo No. A0317-SPN92-180-1609. This shows the forward chassis-bed interface on the M927A1 truck. The gap is a result of the forces induced into the vehicle when it is secured to a flatcar for rail transportation. This mount is located behind the truck cab.





Photo No. A0317-SPN92-180-1611. This photo shows the forward chassis-bed interface of the M927A1 truck. A accommodate frame twisting. The gap shown is induced by the tension in the vehicle tiedown cables at the front wooden strip is used as a barrier between the units. It is tapered at the front end and spring-loaded to and rear of the vehicle.



U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

Photo No. A0317-SPN92-180-1620. This photo shows the M923A1 5-ton truck mount cabled to an instrumented flatcar for rail impact testing.



testing has shown that the shackles used here will withstand the rail transportation environment, while those issued truck to a flatcar for rail transportation. The shackles mounted on the bumper are not the standard issue. Previous Photo No. A0317-SPN92-180-1593. This photo shows the tiedown configuration used to secure the M923A1 5-ton with the truck do not. The stock number for these replacement shackles is NSN 4030-01-222 6037.




Photo No. A0317-SPN92-180-1617. This photo shows an overview of the M923A1 5-ton truck tied down to a flatcar for rail impact testing. Note the front shackles. These are standard issue shackles which failed in a rail mode of transportation. They must be replaced with NSN 4030-01-222-6037.




Photo No. A0317-SPN92-180-1605. This photo shows the M923A1 5-ton truck cabled to a flatcar and coupled to the switch engine, ready for an impact.



(not seen at the right) and caused it to spread far enough to disengage from the pin. The rear shackles should be replaced with NSN 4030-01-222-6037. used for securing the M923A1 5-ton truck to a flatcar for shipment by rail. The shackle sheared off the safety pin Photo No. A0317-SPN92-180-1581. This is typical of the damage that occurs to an undersized schackle when



bed to the M923A1 chassis. The lower bracket was riveted to the truck frame. Rail impact testing caused the lower bracket to slip and shear all three rivets. Field repair was accomplished with 3/8-inch UNF grade 5 bolts. The field Photo No. A0317-SPN92-180-1601. This photo shows the rear mounting brackets that are used to mount the ISO repair also failed.




Photo No. A0319-SPN92-180-1596. This photo shows the rear mounting brackets used to secure the ISO bed to the M923A1 truck. Note the chipped paint on the lower bracket and at the left where the bracket attached to the truck frame. Chipped paint is the first sign of an impending failure.






Photo No. A0317-SPN92-180-1599. This photo shows the remainder of a lower riveted mounting bracket after impact testing sheared the fasteners. A field fix of 3/8-inch UNF grade 5 bolts also failed.



U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

Photo No. A0317-SPN92-180-1594. This photo shows the rear mounting brackets used to secure the ISO bed to the M923A1 chassis. Cracked paint is observed on the mount.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

Photo No. A0317-SPN92-180-1597. This photo shows the rear mounting brackets used to secure the ISO bed to the M923A1 truck chassis. The knife is used to point to the cracked paint between the chassis and mount.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

testing and not having enough strength. It is suggested that this shackle be replaced with NSN 4030-01-222-4089. Photo No. A0317-SPN92-180-1583. This photo shows a separated shackle. It separated as a result of rail impact



U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

Photo No. A0317-SPN92-180-1585. This photo illustrates the extent to which a shackle will deform in a railroad transportation environment. For this reason, it is suggested that the shackle be replaced with NSN 4030-01-222-4089.



SPECIAL NOTES:

- 1. A S-TON M927AL CARGO TRAILER, HAVING DIMENSIONS OF 87-1/2° VIDE BY 381° LONG (402-1/2° VITH VINCH), AND WEIGHING 25,000 POUNDS ENPTY, OR 35,000 POUNDS FULLY LOADED, IS SHOWN SECURED TO A 10°-0° VIDE BY 52°-0° LONG FLAT CAR HAVING 15 STAKE POCKETS. SEE GENERAL NOTE "C" ON PAGE 2.
- 2. THE VEHICLE SHOWN WAS SELECTED AS TYPICAL ONLY AND VEHICLES OF OTHER DIMENSIONS AND VEHICUTS MAY BE SECURED TO A FLAT CAR USING THESE SAME PROCEDURES.
- 3. IF THE VEHICLE BEING LOADED VEIGHS 25,000 POLNOS OF LESS, USE 1/2" STEEL VIRE ROPE IN LIEU OF 5/8" STEEL VIRE ROPE MARKED (1). ALSO, USE 1/2" SIZE CLIPS IN LIEU OF THE 5/8" SIZE CLIPS MARKED (7). AND 1/2" SIZE THOMELES IN LIEU OF THE 5/8" SIZE THOMELES MARKED (8). SEE LOADING AND TIEDDWN PROCEDURES NOTE 2 ON PAGE 4, AND CABLE JOINT A DETAIL ON PAGE 40.

LOAD AS SHOWN (EMPTY VEHICLE)

ITEH	QUANTITY YEIGHT (APPROX)
	333 FBZ,
	TOTAL WEIGHT 25,333 LBS (APPROX.)

LOAD AS SHOWN (FULLY LOADED VEHICLE)

<u>IIB</u>	QUANTITY	VEIGHT (APPROX)
LOAD		28J 000.01
	TOTAL WEIGHT	(XDR99A) 28J EEE, 26

BILL OF MATERIAL				
LUNGER	LINEAR FEET	BOARD FEET		
2" X 4" 2" X 6" 6" X 8"	62 36 10	42 36 40		
NAILS	NO. REDO	POUNOS		
12d (3-1/4") 30d (4-1/2") 40d (5") 60d (6")	30 96 55 16	2 5 3-1/2 1-3/4		
ROPE. STEEL VIPE, 5/8" DIA - 98" REDO 65 LES CLIPS, 5/8" 24 REDO 15 LES TROMBLES, STANDARD, 5/8" 8 REDD 3 LES WATERPROOF PAPER OR BUPLAP AS REDD NIL				


5-TON M927A1 CARGO TRUCK

PAGE 13

PART 7


ACCELEROMETER DATA

M927A1 TRUCK



Anno Cert of USMC M927A1 Truck, Inpact 1 Mar 31 89:23:22 1992

г



noitareleash


Time of Sample Seconds X 1.0000

Anno Cert of USMC M927A1 Truck, Impact 1 Mar 31 09:23:22 1992 5.83 .200 .600 -.200 -.609

0000'T X


Seconds X 2.0000 Time of Sample

Long. Acceleration Truck Bed Cs X 1.6666



Time of Sample Seconds X i.0000

Vert. Acceleration Truck Bed Cs X 1.0000




Time of Sample Seconds X 1.8888

(


1.00 -. 500 . 888

Long. Acceleration




Seconds X 1.0808 Time of Sample

Anno Cert of USMC M927A1 Truck, Inpact 1 Mar 31 89:23:22 1992




Seconds X 1.0000 Time of Sample

Time of Sample Seconds X 1.0000



Γ


Anno Cert of USMC M927A1 Truck, Inpact 1 Mar 31 89:23:22 1992




Seconds X 1.8686 Time of Sample

r

Seconds X 1.0000 Tine of Sample -1.20



Anno Cert of USHC M927A1 Truck, Impact 1 Mar 31 89:23:22 1992



Seconds X 1.0000 Time of Sample

USMC M927A1 Truck, Impact 1 Mar 31 89:23:22 1992 5.91 Anno Cert of .300 -.300 -2.10 906.--1.50

Time of Sample Seconds X 1.0000


1.80 -- 0099 -1.80 -- .688 -

Anno Cert of USMC M927A1 Truck, Inpact 1 Mar 31 89:23:22 1992 6.87 5.99 5.91 5.83 3.88


Seconds X 2.0888 Time of Sample

r

Anno Cert of USMC M927A1 Truck, Impact 2 Mar 31 09:33:89




1 . BBBB Time of Sample × Seconds




Time of Sample Seconds X 1.8888

Vert. Acceleration Truck Bed Cs X 1.0006



Time of Sample Seconds X 1.0000

r




Seconds X 1.0000 Time of Sample

Anno Cart of USMC M927A1 Truck, Inpact 2 Mar 31 89:33:89 1992 4.61 1.20 .400 -.400 -1.20 -2.00

Time of Sample Seconds X 1.0000


Seconds X 1.8888 Time of Sample




Anno Cert of USMC M927A1 Truck, Inpact 2 Mar 31 89:33:89 1992 - .600 -.600 -4.20 -1.80 -3.00

Time of Sample Seconds X 1.0000

Anno Cert of USMC M927A1 Truck, Inpact 2 Mar 31 89:33:89 1992




Seconds X 1.0000 Time of Sample




Seconds X 1.8888 Time of Sample

Anno Cert of USMC M927A1 Truck, Inpact 2 Mar 31 89:33:89 1992




Time of Sample Seconds X 1.8886

Vert. Acceleration Top of Container, NW Cs X 1.0000



Time of Sample Seconds X 2.8888

Mar 31 69:41:19 m Anno Cart of USHC M927A1 Truck, Impact




Long. Acceleration

Time of Sample Seconds X 1.0000


г

9000.1 X Acceleration



Seconds X 2.0000 Time of Sample

Anno Cert of USHC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992




Acceleration

Seconds X 1.0000 Time of Sample

Γ

Vert, Acceleration Truck Bed 55 X 1.0000



Time of Sample Seconds X 1.0000

Anno Cert of USMC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992

Time of Sample Seconds X 1.0000


-2.10

Truck Frame

noitarsfaceA


Seconds X 2.0000

Time of Sample




Anno Cert of USMC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992

Г



Seconds X 1.8888 Time of Sample



Seconds X 2.0000 Time of Sample

2.40 -2.40 -4.00 -4.00 -4.00 -4.15 -4.23

Anno Cert of USHC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992

Time of Sample Seconds X 1.0000


1.68 8.60 -1.69 4.80

Seconds X 1.0000 Time of Sample

Anno Cert of USMC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992


-4.80

Anno Cert of USHC M927A1 Truck, Inpact 3 Mar 31 89:41:19 1992



Time of Sample Seconds X 1.0000

Vert. Acceleration Top of Container, NW Cs X 1.0000




Time of Sample Seconds X 1.0000

2.00


Anno Cert of USMC M927A1 Truck, Inpact 4 Mar 31 10:37:87 1992

r




Seconds X 1.0000 Time of Sample

Time of Sample Seconds X 1.0000




r



0000.1

Seconds X 1.8888 Time of Sample


Vert. Acceleration Truck Bed S X 1.0000



Time of Sample Seconds X E.0000


ſ

Acceleration



r

Seconds X 1.0000 Time of Sample




Seconds X 1.0000 Time of Sample

Time of Sample

Anno Cert of USMC M927A1 Truck, Inpact 4 Mar 31 10:37:07 1992 1.60 -8.00 4.80

Seconds X 1.0000

Long. Acceleration Top of Container Ss X 1.8888



Time of Sample Seconds X 1.0000


1.40 --.000 -1.40 -2.80 4.34 4.54

Acceleration

1992

Anno Cert of USMC M927A1 Truck, Inpact 4 Mar 31 18:37:87


Seconds X 1.8888



r


Seconds X 1.0000 Time of Sample

Long, Acceleration Top of Container, NW Gs X 1.0000




Time of Sample Seconds X 1.8888

Vert. Acceleration Top of Container, NW Gs X 1.8888




Time of Sample Seconds X 1.8888

Time of Sample




Seconds X 1.8088



Roceleration

Seconds X 1.0000 Time of Sample

Cs X 1.0000 Truck Bed Truck Bed




Time of Sample Seconds X 1.0000

Mar 31 11:09:38 1992 n Anno Cert of USMC M927A1 Truck, Inpact .000 8.00 4.00 -8.00


Time of Sample Seconds X 1.0000

Г




Seconds X 1.0000 Time of Sample

1992 5 Mar 31 11:09:38 Anno Cert of USMC M927A1 Truck, Inpact



Time of Sample


1.8888 Seconds X




Time of Sample Seconds X 1.0000

Seconds X 1.0000

Time of Sample




.000 1.20 -1.20 -2.40



Saconds X 1.0000 Time of Sample


Vert, Acceleration Top of Container Gs X 1.8888




Time of Sample Seconds X 1.0000

ı

Time of Sample Seconds X 1.0000




1992 5 Mar 31 11:09:38 Anno Cart of USMC M927A1 Truck, Inpact




Seconds X 1.0000 Time of Sample

M923A1 TRUCK




Anno Cert of USMC M923A1 Truck, Impact 1 Apr 81 18:16:84 1992




Time of Sample Seconds X 1.0000

Anno Cert of USMC M923A1 Truck, Inpact 1 Apr 01 10:16:04 1992




Time of Sample Seconds X 1.0000

Anno Cert of USMC M923A1 Truck, Impact 1 Apr 01 10:16:04 1992




Time of Sample Seconds X 1.0000



Seconds X 1.0000 Time of Sample


1.00 1.00 .200

Anno Cert of USMC M923A1 Truck, Impact 1 Apr 01 10:16:04 1992




Seconds X 2.8888 Time of Sample

Acceleration




Seconds X 1.8888 Time of Sample

-.750 -2.25




Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Inpact 1 Apr 01 10:16:04 1992




Time of Sample Seconds X 1.0000

Seconds X 1,0000 Time of Sample -2.50




Anno Cert of USMC M923A1 Truck, Impact 1 Apr 81 18:16:84 1992




Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Inpact 1 Apr 01 10:16:04 1992



Seconds X 1.0000 Tine of Sample

1992 Apr 81 18:23:59 N Anno Cert of USMC M923A1 Truck, Inpact



Acceleration

Time of Sample Seconds X 1.0000

1992 2 Apr 01 10:23:59 Anno Cert of USMC M923A1 Truck, Inpact .500 .000 -.500

Time of Sample Seconds X 1.0000


-1.00

Acceleration

Г


2 Apr 01 10:23:59 1992 Anno Cert of USMC M923A1 Truck, Impact

Γ




Time of Sample Seconds X 1.0000

Anno Cert of USMC M923A1 Truck, Impact 2 Apr 01 10:23:59 1992



Time of Sample Seconds X 1.0000

Anno Cert of USMC M923A1 Truck, Inpact 2 Apr 01 10:23:59 1992




Acceleration


Time of Sample Seconds X 1.0000

ſ

1.60 .800 . 888 -.800 -1.60 0000 T




Seconds X 1.0000 Time of Sample



0000.

Seconds X 1.0000 Time of Sample


5.02



Long. Acceleration

Saconds X 1.0000 Time of Sample

1992 Anno Cert of USHC M923A1 Truck, Inpact 2 Apr 01 10:23:59




Time of Sample

Seconds X 1.0000

1992 Anno Cert of USMC M923A1 Truck, Inpact 2 Apr 01 10:23:59

r




0000.1

Time of Sample

Seconds X 1.0000

1992 Anno Cert of USMC M923A1 Truck, Impact 2 Apr 81 18:23:59



Long. Acceleration


Seconds X 1.0000 Time of Sample

0000.1 X 20


Time of Sample
Seconds X 1.0000

2 Apr 01 10:23:59 1992 Anno Cert of USMC M923A1 Truck, Impact

Time of Sample Seconds X 1.0000




Acceleration




Seconds X 1.0000 Time of Sample

Acceleration




Saconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Impact 3 Apr 01 10:31:37 1992




Time of Sample Seconds X 1.0000



Seconds X 1.0000 Time of Sample

3 Apr 81 18:31:37 1992 Anno Cert of USMC M923A1 Truck, Inpact



0000 T

Acceleration


1.0000 Tine of Sample Seconds X

٢

Seconds X 1.0006 Time of Sample 3.88

6000.1

Acceleration




Seconds X 1.0000 Time of Sample 3.88

3.96 6.00 3.60 1.20 -1.20 8.40


Anno Cert of USMC M923A1 Truck, Impact 3 Apr Ø1 10:31:37 1992

Ammo Cert of




Seconds X 1.0000 Time of Sample

Vert. Acceleration Top of Front Sixcon Gs X .0100



Time of Sample Seconds X 1.0000

Acceleration




1.0000 Time of Sample Seconds X

Anno Cert of USMC M923A1 Truck, Impact 3 Apr 01 10:31:37 1992 3.96 3.88 1.00 .000 -1.00 -3.60


Time of Sample Seconds X 1.8888

Anno Cert of . USMC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992




Time of Sample Seconds X 1.0000

Anno Cert of USMC M923A1 Truck, Impact 4 Apr 81 13:52:86




Time of Sample Seconds X 1.0000

Anno Cert of USHC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992



Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992




Time of Sample Seconds X 1.0000

Iruck Frame

Acceleration

Anno Cert of USMC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992




Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Inpact 4 Apr Ø1 13:52:06 1992 .400 .200 .000 -.200


Time of Sample Seconds X 1.0000

Seconds X 1.0000 Time of Sample

0000 T




Anno Cart of USMC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992



Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Inpact 4 Apr Ø1 13:52:06 1992




Tine of Sample Seconds X 1.0000

r


•

Anno Cert of USMC M923A1 Truck, Inpact 4 Apr 01 13:52:06 1992




Time of Sample Seconds X 1.0000

Anno Cart of USMC M923A1 Truck, Impact 4 Apr 01 13:52:06 1992




Time of Sample

Seconds X 1.8080



Seconds X 1.8688 Time of Sample


Time of Sample Seconds X 1.0000



Acceleration


r

Apr 81 14:88:86 1992 n Anno Cert of USMC M923A1 Truck, Inpact



Time of Sample Seconds X 1.8888

Anno Cert of USMC M923A1 Truck, Inpact 5 Apr 01 14:00:06 1992



Seconds X 1.8888 Time of Sample

Iruck Frane

Acceleration

1.20 --.400 -.400 -2.00 -1.20


Anno Cert of USMC M923A1 Truck, Inpact 5 Apr 01 14:00:06 1992

Time of Sample Seconds X 1.0000

5.65


5.51

5.23




Seconds X 1.0000 Time of Sample

Time of Sample Seconds X 1.8000



г

Anno Cert of USMC M923A1 Truck, Impact 5 Apr 81 14:88:86 1992




Long. Acceleration Top of Front Sixcon Gs X 1.0808

Time of Sample Seconds X 1.0000

0000 T

Acceleration




Seconds X 1.0000 Time of Sample

Anno Cert of USMC M923A1 Truck, Impact 5 Apr 01 14:00:06 1992 5.65 5.51 5.37 5.23 .032 960.--. 600 -.032

Time of Sample Seconds X 1.0000

Vert, Acceleration Top of Front Sixcon Cs X .0100



Time of Sample Seconds X 1.0000

1992 Apr 01 14:00:06 n Anno Cert of USMC M923A1 Truck, Inpact -.079 -.099 -.120 -.839 -.059

Seconds X 1.0000 Time of Sample

5.65

5.51


5.37

5.23

0000.1 X

Long. Acceleration

Anno-Cert of USMC M923A1 Truck, Impact 5 Apr 01 14:00:06 1992



Acceleration

Time of Sample Seconds X 1.0000

ſ